

Bauten/Mauern	L	H	Stärke	Fläche in m²	Volumen in m³	M verfugen m²	M'Schale Neuaufbau m²	M'Werk Neuaufbau m3	M'Krone Neuaufbau m3	Kr'Abdeckung m2		
M1 Beringmauer												
M1.1.2 Mauerturm	13.00	8.00	1.00	104.00	104.00		104.00		13.00			
M1.2.2 zwischen Brücke und Schildmauer	5.00	3.00	1.00		15.00				5.00			
M1.2.2a	5.00	3.00		15.00		7.50	1.50					
M1.2.2i	5.00	2.00		10.00		5.00	1.00					
M1.3.1 westliche Beringmauer, südlicher Teil	12.00	6.50	1.20		93.60				14.40			
M1.3.1a	12.00	5.00		60.00		18.00	18.00					
M1.3.1i	12.00	8.00		96.00		9.60						
M1.3.2 westliche Beringmauer, mittlerer Teil	27.00	5.00	1.20	135.00	162.00				32.40			
M1.3.2a	27.00	5.00		135.00		67.50	27.00					
M1.3.2i	27.00	1.20		32.40		16.20	6.48					
M1.3.3 westliche Beringmauer, nördlicher Teil	30.00	16.50	1.20	495.00	594.00				36.00			
M1.3.3a	30.00	18.00		540.00		432.00	108.00					
M1.3.3i	30.00	15.00		450.00		45.00						
Gesamt					2072.40	968.60	600.80	265.98	0.00	100.80	0.00	
M2 Schildmauer												
M2.2 Schildmauer, westlicher Teil	15.00	17.50	4		1050.00				60.00			
M2.2a	15.00	20.00		300.00		150.00	90.00					
M2.2i	15.00	15.00		225.00		112.50	67.50					
Gesamt					525.00	1050.00	262.50	157.50	0.00	60.00	0.00	

## Sanierung Burgruine Farnsburg 2019-2022

## Mauerwerk mit Sanierungsmassnahmen (Schätzung)

<b>B1 Palas</b>																			
M21.1																			
Ostmauer	9		1.6			14.40								14.40					
M21.1a	9	7		63.00			6.30		6.30										
M21.1i	9	1.2		10.80			1.08		1.08										
M21.2																			
Mauer zwischen B1/1 und B1/2	7.3	3.5	0.7			17.89								5.11					
M21.2i	7.3	3.5		25.55			2.56		2.56										
M21.3																			
Mauer zwischen B1/2 und B1/3	8.4	2.5	0.7			14.70								5.88					
M21.3a	8.4	2.5		21.00															
M21.4																			
Nordmauer Ost	7.5	2.5	2.5			46.88								18.75					
M21.4a	7.5	2.5		18.75			9.38		9.38										
M21.4i	7.5	2.5		18.75			9.38		9.38										
M21.5																			
Nordmauer Mitte Ost	5.5	1.30	2.5			17.88								13.75					
M21.6a	5.5	1.4		7.70			0.77												
M21.6i	5.5	1.2		6.60			0.66		0.66										
M21.6																			
Nordmauer West 1	3.5	3	2.5			26.25					7.00			8.75					
M21.6a	3.5	3		10.50			5.25		1.05										
M21.6i	3.5	3		10.50			5.25		1.05										
M21.7																			
Nordmauer West 2	2	1.93	0.7			2.70								1.40					
M21.7a	2	0.85		1.70			0.85		0.34										
M21.7i	2	3		6.00			3.00		1.80										
M21.8																			
Mauer zwischen B1/1 und B1/2	7.5		0.5			3.75								3.75					
M21.8a	7.5	1.1		8.25			1.65		0.83										
M21.8i	7.5	1.1		8.25			1.65		0.83										
<b>Gesamt</b>					<u>200.85</u>		<u>140.68</u>		<u>47.77</u>		<u>35.24</u>		<u>7.00</u>		<u>71.79</u>		<u>0.00</u>		

**Sanierung Burgruine Farnsburg 2019-2022**
**Mauerwerk mit Sanierungsmassnahmen (Schätzung)**

<b>B2 Amts- und Wohngebäude</b>																			
M201																			
Nordmauer	10.5	14	1.2			176.40								12.60					
M201a	10.5	14		147.00			102.90		14.70										
M201i	10.5	14		147.00			102.90		14.70										
M202																			
Ostmauer	7	0.95	0.9			5.99								6.30					
M202a	7	0.95		6.65			0.67												
M202i	7	0.95		6.65			0.67												
M203																			
Südmauer	10.5	1	1			10.50								10.50					
M203a	10.5	1		10.50			1.05		0.11										
M203i	10.5	1		10.50			1.05		0.11										
Gesamt					328.30		192.89		209.23		29.61		0.00		29.40		0.00		
<b>B 3 Kapelle</b>																			
M301																			
N-S-Mauer	6.7	5	0.8			26.80										5.36			
M301a	6.7	5		33.50			10.05		6.70										
M301i	6.7	5		33.50			10.05		6.70										
M302																			
W-O-Mauer																			
M302a	12.5	10	0.5	125.00			62.50		50.00					6.25					
Gesamt					67.00		26.80		82.60		63.40		0.00		6.25		5.36		

## Sanierung Burgruine Farnsburg 2019-2022

## Mauerwerk mit Sanierungsmassnahmen (Schätzung)

<b>B 6 Blauer Turm</b>																			
M601	12	3.80	2.8			127.68											33.60		
M601a	17	6		102.00			10.20												
M601i	7.5	1.6		12.00			1.20		0.00										
Strebepfeiler M602	2.5	4	1	10.00		10.00	1.00		2.00										
<b>Gesamt</b>					<u>124.00</u>	<u>137.68</u>		<u>12.40</u>	<u>2.00</u>	<u>0.00</u>	<u>0.00</u>	<u>33.60</u>							
<b>B7 Brunnenhaus</b>																			
M701																			
N-Mauer	8.6		0.8			6.88						6.88							
M701a	8.6	5	0.8	43.00			4.30		21.50										
M701i	8.6	0.9	0.8	7.74			0.77		2.32										
M702																			
Mauer, Bereich Bunker	11	6	0.8			52.80						8.80							
M702a	11	6	0.8	66.00			6.60												
M704																			
Westmauer	5.5	2	1			11.00						5.50							
M704i	5.5	2	1	11.00			1.10												
M703																			
Brunnenrand	12.5	0.70	0.8			7.00						10.00							
M703a	12.5	0.6	0.8	7.50			0.75		6.00										
M703i	12.5	0.8	0.8	10.00					8.00										
<b>Gesamt</b>					<u>145.24</u>	<u>77.68</u>		<u>13.52</u>	<u>37.82</u>	<u>0.00</u>	<u>31.18</u>	<u>0.00</u>							
<b>B17 Bollwerk</b>																			
M16.1																			
Drittel Ost	5.3	5	3.3	26.50		87.45	13.25		7.95			17.49							
M16.2																			
Drittel Süd	6.8	3	3.3	20.40		67.32	10.20		6.12			22.44							
M16.3																			
Drittel West	7.6	3	3.3	22.80		75.24	11.40		6.84			25.08							
M16.4																			
N-Seite	9.8	1.6	0.8	15.68		12.54	7.84		4.70			7.84							
<b>Gesamt</b>					<u>85.38</u>	<u>242.55</u>		<u>42.69</u>	<u>25.61</u>	<u>0.00</u>	<u>55.36</u>	<u>0.00</u>							

<b>B18 Treppe und Podest zum Palas</b>																			
M218.1																			
N-Mauer Podest	5.5	2.5	2.8				38.50								15.40				
M218.1a	5.5	2.5			13.75			1.38			1.38								
M218.2																			
Treppenwange	4.5	1.5	0.5				3.38									0.00			
M218.2a	4.5	1.5			6.75			3.38			3.38								
M218.3																			
Westmauer Podest	2.8	3	0.5				4.20									0.00			
M218.3a	2.8	3			8.40			0.84			1.68								
M218.4																			
Treppe	4.5	2	1.8				16.20									0.00			
M218.4	4.5	2			9.00			4.50						4.50					
M218.5																			
Podest	5		2.8				14.00									14.00			
Gesamt						37.90		76.28		10.09		6.43		0.00		19.90		14.00	
<b>B19 Treppe zum Podest unterhalb von B20</b>																			
M219.1																			
Treppe	10.5		2.5				26.25												
M219.2																			
Treppenwange	11	3	0.9				29.70												
M219.2W	11	3	0.9		33.00			16.50		9.90									
Gesamt						33.00		27.98		16.50		9.90		0.00		0.00		0.00	
<b>B20 Lange Stiege</b>																			
M220.1																			
Treppe	23		2.2				50.60							50.60		0.00			
M220.2																			
Treppenwange West	23	1.40	0.7				22.54									16.10			
M220.2a	23	2.5			57.50														
M220.2i	23	0.3			6.90														
M220.3																			
Treppenwange Ost	23		0.7																
M220.3	23	20	0.7		460.00			230.00		92.00									
Gesamt						524.40		73.14		230.00		92.00		0.00		50.60		16.10	
<b>B4 Pfisterhaus</b>																			
M4.1																			
Südmauer	4.2	9.43	0.8				31.67							3.36		0.00			
M4.1i	4.2	0.85						0.10											
M4.1a	4.2	18			75.60			37.80		7.56									
M4.2																			
Mauergeviert	7.5	1	0.6		7.50			3.75											
Gesamt						83.10		31.67		41.65		7.56		0.00		3.36		0.00	

## Sanierung Burgruine Farnsburg 2019-2022

**Mauerwerk mit Sanierungsmassnahmen (Schätzung)**

[illegible]